



Report Number: QIP-ASI1331059

Audit Date : 13 May, 2013 Expiry Date : 12 May, 2014

This report is issued by Focus Technology Co., Ltd. (Made-in-China.com) and the supervising inspectorate (SGS-CSTC Standards Technical Services Co., Ltd.) to confirm that:

Company Name : Yongkang Huaxiong Die-Casting Factory

永康市华雄压铸厂

Showroom : http://ykhuaxiong.en.made-in-china.com/

: Guanshanbei Industrial Zone, Tangxian Town, Yongkang, Jinhua, **Address**

Zhejiang, China

Product : Casting, Motorcycle Wheel

has been on site audited for the Following Scope of Activity

1. General Information

2. Production Capacity & Quality Control

3. Photos



General Comments:

Yongkang Huaxiong Die-Casting Factor is a manufacturer with 47 employees; it was established in 2003, located in Guanshanbei Industrial Zone, Tangxian Town, Yongkang, Jinhua, Zhejiang, China. The company occupy an area of more than 2,500 square meters.

Sign for and on behalf of

SGS-CSTC Standards Technical Services Co., Ltd.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and to adjust accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any face of the safely and to the safely and the safely an

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com
Page No.: 1 of 9

中国・江苏・南京・中山南路315号瑞华大厦19楼

邮编:210001

19/F, Ruihua Building, No.315, Zhongshan South Road, Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 t (86-25) 58075282 f (86-25) 83407773



SUPPLIER ASSESSMENT REPORT

	Yongkang Huaxiong Die-Casting Factory 永康市华雄压铸厂	
Audited Site:	Guanshanbei Industrial Zone, Tangxian Town, Yongkang, Jinhua, Zhejiang, China	

Consigner of Assessment	Made-in-China.com		
Audit Type			
	☐ Re-audit	To II	2
Valid Date	From 13 May, 2013 to 12 May, 2014	Verify Report	www.sgs.com
Auditor	Devin Zhang	Reviewed by	Roger Wang

CONTENTS

Part A: General Information

Section 1: Company Overview Section 2: Human Resources

Part B: Foreign Trade Capacity

Section 1: Export Overall Situation Section 2: Export Business Capacity Section 3: Supplier Management Section 4: After-sales Service Capacity

Part C: Product Research & Development Capacity

Section 1: Product Research & Development Capacity

Part D: Management System and Product Certification

Section 1: Management System(s) and Product Certification

□ Part E: Production Capacity & Quality Control

Section 1: Production Capacity Section Section 2: Production Process Control

Part F: Financial Position

Section 1: Financial Data

Section 2: Key Performance Indications

Section 3: Banking

Section 4: Product Insurance

Part G: Working Environment

Section 1: Working Environment

Part H: Energy Saving and Emission Reduction

Section 1: Environmental Management Section 2: Water, Gas and Noise Control

Part I: Industry Information

Section 1: Industry Information

Part J: Photos

Section 1: Photos of Documents Section 2: Photos of Company

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any factoribating cole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations under the transaction from exercising all their rights and obligations to the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest of the law.

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 2 of 9

19/F, Ruihua Building, No.315, Zhongshan South Road, Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼

邮编:210001

t (86-25) 58075282 f (86-25) 83407773





Part A: General Information

Section 1: Company Overview

1.1 Legal Validity				
Does the company have a valid business license?	☐ Yes ☐ No ☐ Others	Registration Number	330784000007115	
Year of established	25 Jun., 2003	Valid Date	/	
Registered address	No. 17, Guanshan South Road, Tangxian 4 Village, Tangxian Town, Yongkang City			
Actual address	Guanshanbei Industrial Zone, Tangxian Town, Yongkang, Jinhua, Zhejiang, China			
Is the annual review done by local authority (Industrial & Commercial Bureau)?	Refer to business license provided; it was reviewed in year 2012.			
Registered capital	N/A			
Paid-in capital	N/A			
Name of legal representative	Mr. Xiaoliang Shi			
Business scope	Special item: None Normal item: Processing of aluminium die-casting. (For pre-permitted and special approved items should be operated after register and obtained related licenses.)			
1.2 Basic Information	1			
Contact person	Mr. Shi	Email	cnhuaxiong@126.com	
Phone number	0086-579-87502992	Fax number	0086-579-87502396	
URL/Web address	http://ykhuaxiong.en.made-in-china.com			
Company type				
Type of ownership	☐ Limited Company ☐ Public Company ☐ Foreign joint venture ☐ State-Owned ☐ Private Owner ☐ Wholly foreign-owned enterprises			
Subsidiary company	The company did not provide subsidiary company information to auditor.			
Products manufactured / sold scope	Casting, Motorcycle Wheel			
1.3 Company Building Information				
According to: ☐ Land certificate ☐ Lease agreement ☐ Compare the certificate ☐ Compare the cer				
The company area 2,500 square meters. The land occupies 2,367.7 square meters. (The owner of the land is the subsidiary company) The offices occupy 500 square meters. The workshops occupy 2,000 square meters.				

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the content of the content

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 3 of 9


> 19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001

t (86-25) 58075282 f (86-25) 83407773





Section 2: Human Resources



Remark: Above information of key staff was based on interview with company representative.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any factoripary cole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents by unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest of the law.

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 4 of 9

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001

t (86-25) 58075282 f (86-25) 83407773



Part E: Production Capacity & Quality Control

Section 1: Production Capacity

1.1 Production Workflow Chart



1.2 Products Situation (Top three Product Categories)

Product	Price range	Min. order quantity	Top monthly output	Average monthly output	Total in 2012
Motorcycle Wheel	RMB 100-400	100 PCS	/	/	/

1.3 Main Facilities

Picture	Facility name	Brand or Country/Region of origin	Target Value/machine*day	Quantity
	Die casting machine	China	/	4
	Lathe	China	/	5

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the Company's cole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents by unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest example.

Aftention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com
Page No.: 5 of 9

邮编:210001

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China **210001** t(86-25) 58075282 f(86-25) 83407773

中国・江苏・南京・中山南路315号瑞华大厦19楼

t (86-25) 58075282 f (86-25) 83407773 t (86-25) 58075282 f (86-25) 83407773



2.1 Pro	2.1 Production Process Control				
Item	Content	Observations /Comments			
1	Product R&D capacity	☐ Own brand☑ ODM☑ OEM			
2	Are the environmental conditions, such as tidiness and cleanliness being controlled and suitable for the operation performed?	□ Very tidy☑ Normal□ Need to improve□ Very poor			
3	Are the necessary items /documents provided at appropriate location and under control?	 ☐ Work Instructions /procedures ☑ Workmanship standard /acceptance ☐ Golden sample /Approval sample ☐ Product picture ☐ Verbal by workshop director 			
4	Are written instructions available for incoming material inspections /testing? Is the relevant record maintained?	 ☐ Has instructions and uniformly followed ☐ Has instruction but no written records ☑ Materials checked by storage staff 			
5	Are written inspections /testing instructions available for finished products? Is the relevant record maintained?	 ☐ Have instructions and uniformly followed ☐ Have instruction but no written records ☑ Finished product checked by packing staff 			
6	What type of inspection is used for finished products?	 □ Random inspection □ Visual inspection □ Function inspection ☑ 100% inspection ☑ Visual inspection ☑ Function inspection 			
7	Are non-conforming units clearly marked/ segregated to prevent accidental dispatch?	☑ Marked and segregated☐ Segregated but not marked clearly☐ Not found on site			
8	How are the non-conforming units handled?	 ☐ Repaired and re-inspection ☐ Picked out ☐ Used under control ☐ Others: Recycle 			

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the content of the content of the content of the intervention only and within the limits of Client's instructions, or a transaction from exercising all their rights and obligations under the transaction documents any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

**Renting To check the supplementation of the content or appearance of the supplementation or appearance of

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 6 of 9





Part J: Photos

Section 1: Photos of Documents





This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safety and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the content of the content of the content of the intervention only and within the limits of Client's instructions, if any the content of the conte

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com Page No.: 7 of 9

邮编:210001

19/F, Ruihua Building, No.315, Zhongshan South Road, Nanjing, Jiangsu, China 210001 t (86-25) 58075282 f (86-25) 83407773

t (86-25) 58075282 f (86-25) 83407773



Section 2: Photos of Company

Description: Company Gate



Description: Workshop



Description: Workshop



Description: Office



Description: Workshop



Description: Workshop



This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the confidence of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest nt of the law.

uthenticity of testing /inspection report & certificate, pleas se contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com

Page No.: 8 of 9

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t(86-25) 58075282 f(86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼 邮编:210001

t (86-25) 58075282 f (86-25) 83407773







-- End of the Report --

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and sadily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the same sadily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the same sadily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the same sadily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any the same sadily accessible portions of the constant of the content of the content of the content of the safety and content of the safety and content of the safety and content of the c

uthenticity of testing /inspection report & certificate, please contact us at telephone: (86-755)83071443, or email: CN.Doccheck@sgs.com

Page No.: 9 of 9

19/F,Ruihua Building,No.315,Zhongshan South Road,Nanjing, Jiangsu, China 210001 t(86-25) 58075282 f(86-25) 83407773 中国・江苏・南京・中山南路315号瑞华大厦19楼

邮编:210001

t (86-25) 58075282 f (86-25) 83407773